## **DISTRICT ROUTE TOWN DRAFT Route Log and Progress Chart** Please Note: Errors and Omissions May Exist. ROCHESTER **VT-73** Contact the VTrans Mapping Section with questions or concerns. Base Map ROCHESTER CHITTENDEN 1 in = 0.5 milesStick Diagram Town Center STRUCTURE DESCRIPTIONS Intersecting State Routes (excl. ramps/approaches) Other Intersecting Highways, Ramps, Bridge 12D: Culvert - 1962 ++++++ Railroad Crossings Primary Structures Structure No. 300162012D14151 Length: 10' Secondary Structures Under Clearance: 11.0' Divided State Highway Facility Carried: VT73 State Highway Structure Type: CGMPP Features Intersected: BRANDON BROOK Divided Town Highway Brandon Brook Brandon Brook Brandon Brook Maintenance: State ---- Town Highway Streams (Hydraulic Structure) Bridge 12E: Town Boundary Culvert - 1962 - - - Village/UC Boundarie Structure No. 300162012E14151 --- District Boundaries Length: 12' Under Clearance: 8.0' o - o - State/Town Highway Change Facility Carried: VT73 --- Divided Highway Limits Structure Type: CGMPPA ---- Ghost Section Boundary Features Intersected: BRANDON BROOK ----- Federal Urban Area Limits Maintenance: State Scale: 1 INCH = 2,000 FEET Bridge 13: Culvert (Arch) - 2014 Structure No. 200162001314152 Length: 53' Facility Carried: VT 73 ML Travellane 35 36 37 32 28 29 28 Structure Type: PRECAST CONC ARCH Roadway Features Intersected: BRANDON BROOK Road Widths Lane Count Maintenance/Ownership: State Bridge <mark>14</mark>: Tee Beam - 1927 Subbase Structure No. 200162001414152 Length: 39' 95.5 5.9 3.6 5.4 4.3 Curves Width: 30.0' Facility Carried: VT 73 ML Structure Type: CONCRETE T-BEAM -10.0 Features Intersected: BRANDON BROOK Grades Surface: Bituminous Maintenance/Ownership: State **Guardrails** Culvert - 2013 Structure No. 300162014A14151 **Rumblestrips** Length: 7' Under Clearance: 3.42' Facility Carried: VT73 Structure Type: SEGMENTAL RC BOX Features Intersected: BROOK Maintenance: State Bridge 15: Tee Beam - 2014 Structure No. 200162001514152 Length: 71' Width: 32.0' Facility Carried: VT 73 ML 1990: HMA 2402 Historic Projects 1984: HMA 2536 Structure Type: PRESTRESS NEXT BEAM Features Intersected: BRANDON BROOK Surface: Bituminous Maintenance/Ownership: State 1984: HMA 2536 Bridge <mark>16</mark>: Tee Beam - 2014 Structure No. 200162001614152 1972: Unknown Length: 65' S-FLH 0162(3) 1957: ST 191-P 1957: ST 191-S Width: 28.1' Facility Carried: VT 73 ML Structure Type: PRESTRESS NEXT BEAM Features Intersected: CORPORATION BROOK District 4 - DMF Maintenance Rochester Garage District 4 - DMF Maintenance Rochester Garage **Maintenance Garage** Surface: Bituminous Maintenance/Ownership: State Speed Zone Stringer/multi-beam or girder - 1984 Structure No. 200162001714152 Length: 102' **Functional Class** Width: 32.8' Facility Carried: VT 73 ML Structure Type: WELDED GIRDER Features Intersected: WEST BRANCH ( National Highway System Surface: Bituminous Maintenance/Ownership: State **Limited Access Highway** Culvert - 1957 Structure No. 300162001814151 Length: 7' **Customer Service Level** Under Clearance: 5.0' Facility Carried: VT73 Structure Type: ACCGMPPA **Traffic Counters** Features Intersected: BROOK

