




DISTRICT	TOWN	ROUTE
2, 4	WEATHERSFIELD, WINDSOR, SPRINGFIELD	I-91



Road Widths	Travellane	Roadway	Lane Count	Base	Subbase
			24		
			40		
			2		
			Two 7 1/2" Cr. Stone Base Courses		
			24" Crushed Rock		

Curves	Grades
	-3.2
	+4.2
	-5.3
	+4
	-2
	+2.2
	-5
	-3
	-4.8
	+2.5
	-6
	+2
	-3.8
	+2.8
	-3.7

Guardrails

Rumblestrips

Historic Projects
2011: IM CULV17
1989: IR 091-115
1990: IR DECK27
1988: IR 091-119
1985: IR 091-148
1992: IR 091-120
1979: IR F 091-143
1979: IR 191-145
1981: IR 091-115
1985: IR 191-120/C1
1985: IR 191-127/STAGE 2
2018: BM 19202
1985: IR 191-120/C2
1985: IR 191-127/STAGE 2

Maintenance Garage
District 2 - DMF Maintenance Rockingham Garage

Speed Zone

Functional Class
1

National Highway System
NHS - Interstate

Limited Access Highway
Full

Customer Service Level
Interstate Or Divided Highway

Traffic Counters
Y075

AAADT	2020	2019	2018	2017	2016
	4867	6489	13000	12900	12700

Crash Locations	Year	Section
	(Incomplete) 2021	HCL Section No. 511
	2020	HCL Section No. 506
	2019	HCL Section No. 508
	2018	HCL Section No. 363
	2017	HCL Section No. 620
		HCL Section No. 362

## STRUCTURE DESCRIPTIONS

<p><b>Bridge 29-3:</b> Culvert - 1965 Structure No. 30009129-314201 Length: 9' Under Clearance: 10.0' Facility Carried: I91 Structure Type: CGMPP ALUM SLEEVE Features Intersected: BROOK Maintenance: State</p>	<p><b>Bridge 32-1:</b> Culvert - 1966 Structure No. 30009132-114231 Length: 6' Under Clearance: 6.5' Facility Carried: I91 Structure Type: CGMPP Features Intersected: BROOK Maintenance: State</p>
<p><b>Bridge 29-4:</b> Stringer/multi-beam or girder - 1965 Structure No. 201420D29414201 Length: 279' Facility Carried: TR 51 Structure Type: 5 SP CONT ROLLED BM Features Intersected: I 91 UNDER TH NO 51</p>	
<p><b>Bridge 29-5:</b> Culvert - 1965 Structure No. 30009129-514201 Length: 6' Under Clearance: 6.5' Facility Carried: I91 Structure Type: CGMPP Features Intersected: BROOK Maintenance: State</p>	
<p><b>Bridge 29-6:</b> Culvert - 1965 Structure No. 30009129-614201 Length: 9' Under Clearance: 10.0' Facility Carried: I91 Structure Type: CGMPP Features Intersected: BLOOD BROOK Maintenance: State</p>	
<p><b>Bridge 29-7N:</b> Culvert - 1965 Structure No. 300091297N14201 Length: 8' Under Clearance: 8.0' Facility Carried: I91 Structure Type: CGMPP W SLEEVE Features Intersected: BROOK Maintenance: State</p>	
<p><b>Bridge 29-9:</b> Culvert - 1965 Structure No. 30009129-914201 Length: 6' Under Clearance: 6.0' Facility Carried: I91 Structure Type: ACCGMPP Features Intersected: CATTLEPASS Maintenance: State</p>	
<p><b>Bridge 29-10:</b> Culvert - 1965 Structure No. 200091291014202 Length: 21' Facility Carried: I91 ML Structure Type: TWIN CELL RC BOX Features Intersected: MILL BROOK Maintenance/Ownership: State</p>	
<p><b>Bridge 30N:</b> Stringer/multi-beam or girder - 1965 Structure No. 200091030N14202 Length: 219' Width: 30.0' Under Clearance: 15.0' Facility Carried: I91 ML Structure Type: 3 SP CONT ROLLED BM Features Intersected: I91 OVER VT 131 Surface: Bituminous Maintenance/Ownership: State</p>	
<p><b>Bridge 30-1:</b> Culvert - 1966 Structure No. 30009130-114201 Length: 8' Under Clearance: 8.5' Facility Carried: I91 Structure Type: CGMPP Features Intersected: BROOK Maintenance: State</p>	
<p><b>Bridge 31:</b> Stringer/multi-beam or girder - 1965 Structure No. 2014200D3114201 Length: 251' Facility Carried: TR 37 Structure Type: 4 SPAN ROLLED BEAM Features Intersected: I 91 UNDER TH NO 37</p>	
<p><b>Bridge 32:</b> Stringer/multi-beam or girder - 1965 Structure No. 2014230D3214231 Length: 321' Facility Carried: VT 0044A Structure Type: 4 SPAN ROLLED BEAM Features Intersected: I 91 UNDER VT 44A</p>	