Route Log Progress Chart


DRAFT Please Note: Errors and Omissions May Exist.


Contact the VTrans Mapping Unit with questions or concerns.

DISTRICT TOWN ROUTE

Min-0536

JAMAICA





| Stringer/multi-beam or girder - 1936 Structure No. 101309002713091 Length: 57' Width: 27.8' Facility Carried: C2001 Bridge Type: ROLLED BEAM Features Intersected: N. BR. BALL MT.BROOK |
|---|
| Surface: Bituminous |
| Maintenance/Ownership: Town |
| Bridge 26: Stringer/multi-beam or girder - 1982 Structure No. 101309002613091 Length: 80' Width: 27.0' Facility Carried: C2001 Bridge Type: ROLLED BEAM Features Intersected: BALL MTN. BROOK Maintenance/Ownership: Town |

DESCRIPTION BLOCK

Maintenance/Ownership: Stringer/multi-beam or girder - 1978 Structure No. 101309002513091 Length: 78' Width: 22.6' Facility Carried: C2001 Bridge Type: ROLLED BEAM Features Intersected: BALL MTN. BROOK Maintenance/Ownership: Town

Bridge <mark>22</mark>: Stringer/multi-beam or girder - 1939 Structure No. 101309002213091 Length: 56' Width: 25.1' Facility Carried: C2001 Bridge Type: ROLLED BEAM Features Intersected: BALL MTN. BROOK Maintenance/Ownership: Town