




DISTRICT	TOWN	ROUTE
9, 7	SHEFFIELD, WHEELOCK, BARTON, GLOVER	I-91



Road Widths	Travellane, Roadway, Lane Count, Base, Subbase	24, 40, 2	Two 7 1/2" Plant Mix Base Courses, 24" Crushed Rock
Curves			
Grades		+5, +3, +5, +3.7, +5, +5, -4.2	
Guardrails			
Rumblestrips			
Historic Projects			2011: IM SURF(22), 2012: IM MEMB(29), 2002: IM 91-3(10), 1989: IR 091-3(4), 1979: I 91-3(8) STAGE 3, 1972: I 91-3(15) STAGE 2, 1973: I 91-3(10) C3, 1973: I 91-3(10) C4, 1973: I 91-3(10) C5
Maintenance Garage			District 7 - HWY Maintenance Lyndon Garage, District 9 - HWY Maintenance Barton Garage
Speed Zone			
Functional Class			1
National Highway System			NHS - Interstate
Limited Access Highway			Full
Customer Service Level			Interstate Or Divided Highway
Traffic Counters			
AADT	2018, 2017, 2016, 2015, 2014		4800, 4900, 5000, 5100, 4900
Crash Locations	2018, 2017, 2016, 2015, 2014		HCL Section No. 729, HCL Section No. 533, HCL Section No. 727, HCL Section No. 120, HCL Section No. 530, HCL Section No. 729

STRUCTURE DESCRIPTIONS

Culvert 98-2:
Culvert - 1973
Structure No. 30009198-203171
Length: 7'
Under Clearance: 7.5'
Facility Carried: I91
Structure Type: CGMPP
Features Intersected: BROOK
Maintenance: State

Culvert 98-3N:
Culvert - 1973
Structure No. 300091983N03121
Length: 6'
Under Clearance: 7.0'
Facility Carried: I91
Structure Type: CGMPP
Features Intersected: BROOK
Maintenance: State

Bridge 100N:
Stringer/multi-beam or girder - 1972
Structure No. 200091100N03122
Length: 145'
Width: 39.2'
Under Clearance: 13.67'
Facility Carried: I 91 ML
Structure Type: 3 SP CONT ROLLED BM
Features Intersected: I 91NB OVER TH NO 1
Surface: Bituminous
Maintenance/Ownership: State

Culvert 1002:
Culvert - 1973
Structure No. 300091100203121
Length: 7'
Under Clearance: 8.0'
Facility Carried: I91
Structure Type: CGMPP
Features Intersected: BROOK
Maintenance: State

Culvert 1004:
Culvert - 1973
Structure No. 300091100403121
Length: 7'
Under Clearance: 7.5'
Facility Carried: I91
Structure Type: CGMPP
Features Intersected: BROOK
Maintenance: State

Culvert 101-N:
Culvert - 1973
Structure No. 300091101N03121
Length: 18'
Under Clearance: 16.0'
Facility Carried: I91
Structure Type: CGMPP
Features Intersected: TH-12 UNDER I-91
Maintenance: State

Culvert 1012N:
Culvert - 1973
Structure No. 300091H12N03121
Length: 7'
Under Clearance: 7.58'
Facility Carried: I91
Structure Type: CGMPP
Features Intersected: BROOK
Maintenance: State

Historic Projects <ul style="list-style-type: none"> Unknown Bituminous Concrete Retreatment Resurface Bituminous Mix Skinny Mix Bituminous Seal 	Functional Class <ul style="list-style-type: none"> 1 - Interstate System 2 - Other 3 - Principal Arterial 4 - Minor Arterial 5 - Major Collector 6 - Minor Collector 	Curves <ul style="list-style-type: none"> Left Right 	Grades <ul style="list-style-type: none"> grade up grade down 	Traffic Counters <ul style="list-style-type: none"> Continuous (CTC) Weigh-In-Motion (WIM) Short-Term, Scheduled Short-Term, Unscheduled 	Crash Locations <ul style="list-style-type: none"> Fatal Injury Property Damage Only Unknown Crash Type 	Mileage by Functional Class By Sheet 91-3 1 - Interstate 9.000	Mileage by Town By Sheet ETE - I091-0000 9.0 of 177.432	DISTRICT 9, 7	TOWN SHEFFIELD, WHEELOCK, BARTON, GLOVER	Date: 12/03/19	ROUTE I-91 ETE mileage: 144.0 to 153.0
---	---	--	---	--	---	--	---	-------------------------	--	-----------------------	---