## Trans Working to Get You There Vermont Agency of Transportation Base Map


## **Route Log and Progress Chart**

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Section with questions or concerns.









STRUCTURE DESCRIPTIONS
ridge <mark>18</mark> : ulvert - 1956 tructure No. 300221001814161
ength: 7' nder Clearance: 7.0'
/eight Limit: 0 acility Carried: VT107 tructure Type: ACCGMPP
eatures Intersected: BROOK spection Date: 9/2018 aintenance: State
ridge <mark>20</mark> : ulvert - 1969 tructure No. 300221002014161
ength: 6' nder Clearance: 6.0'
/eight Limit: 0 acility Carried: VT107 tructure Type: ACCGMPP
eatures Intersected: BROOK spection Date: 9/2018 aintenance: State
nknown <mark>20A:</mark> nknown
tructure No. 200089026S14162 tructure Type: Unknown
nknown <mark>20B</mark> : nknown
tructure No. 200089026N14162 tructure Type: Unknown
ridge <mark>21</mark> : tringer/multi-beam or girder - 1937 tructure No. 200150002114162
ength: 148' eight: 100.0'
/idth: 30.0' /eight Limit: 0 acility Carried: VT 00107 ML
tructure Type: 3 SPAN ROLLED BEAM eatures Intersected: 2ND BRANCH WHITE R.
urface: Bituminous spection Date: 7/2021 aintenance/Ownership: State