Unknown


Resurface

■ Bituminous Mix

For More Information Contact - Vermont Agency of Transportation, Policy, Planning and Intermodal Development Division - Mapping Section, 219 North Main Street, Barre, VT 05641 Telephone: 802-828-2600.

Route Log and Progress Chart


DISTRICT TOWN DRAFT Please Note: Errors and Omissions May Exist. CANAAN Contact the VTrans Mapping Section with questions or concerns.



ROUTE

VT-114





STRUCTURE DESCRIPTIONS
Bridge 45: Culvert - 1957 Structure No. 300320004505061 Length: 13' Under Clearance: 8.0' Weight Limit: 0 Facility Carried: VT114 Structure Type: CGMPA Features Intersected: BROOK Inspection Date: 10/2018 Maintenance: State
Bridge 46: Culvert - 1957 Structure No. 300320004605061 Length: 6' Under Clearance: 6.0' Weight Limit: 0 Facility Carried: VT114 Structure Type: ACCGMPP Features Intersected: BROOK Inspection Date: 10/2022 Maintenance: State
Bridge 48: Stringer/multi-beam or girder - 1984 Structure No. 200320004805062 Length: 58' Height: 100.0' Width: 33.0' Weight Limit: 0 Facility Carried: VT 00114 ML Structure Type: ROLLED BEAM Features Intersected: LEACH CREEK Surface: Bituminous Inspection Date: 7/2021 Maintenance/Ownership: State
Bridge 52: Stringer/multi-beam or girder - 1980 Structure No. 200320005205062 Length: 90' Height: 100.0' Width: 33.0' Weight Limit: 0 Facility Carried: VT 00114 ML Structure Type: WELDED PLATE GIRDER Features Intersected: LEACH CREEK

Stringer/multi-beam or girder - 1990 Structure No. 200320B05305062 Length: 240' Height: 100.0' Width: 40.0' Weight Limit: 0 Facility Carried: VT114,MAIN STREET Structure Type: Unknown Features Intersected: CONNECTICUT RIVER Surface: Bituminous Inspection Date: 8/2022 Maintenance/Ownership: State

Features Intersected: LEACH CREEK

Surface: Bituminous Inspection Date: 7/2021 Maintenance/Ownership: State