
## Trans Working to Get You There Vermont Agency of Transportation

## **Route Log Progress Chart**

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Unit with questions or concerns.

DISTRICT TOWN ROUTE

3 RUTLAND TOWN BUS-4



**DESCRIPTION BLOCK** 

Bridge <mark>B4-3</mark>: Stringer/multi-beam or girder - 1959 Structure No. 203200B4-311202

Facility Carried: US 00BR4 BUS. Bridge Type: WELDED PLATE GIRDER

Maintenance/Ownership: State

Bridge <mark>B4-4</mark>: Stringer/multi-beam or girder - 1959 Structure No. 203200B4-411202

Facility Carried: US 00BR4 BUS.

Maintenance/Ownership: State

Bridge Type: 2SP ROLLLED BEAM Features Intersected: OTTER CREEK

Bridge B4-5: Girder and floorbeam system - 1959

Height: 0.0'
Facility Carried: RAILROAD
Bridge Type: RIVETED TWO GIRDER

Features Intersected: VT RR OVER BR US 4

Structure No. 203200B4-511202

Features Intersected: CLARENDON RIVER

Length: 116' Width: 55.8'


Length: 147'

Width: 66.8'

Length: 132'

Surface: Bituminous

Surface: Bituminous



			- 1141111						i		1	
Historic Projects	Functional Class	Curves	Road Widths	AADT	Mileage by Functional Class By Sheet		Mileage by Town By Sheet					
Retreatment Bituminous Gravel	├──+ 1 <b>──</b> ─ 7 <b>──</b> ─ 12 <b>──</b> ─ 17	Left	<b>←</b> (ft)	(count)	3200 14 - Urban - Principal Arterial - Other	0.997	RUTLAND TOWN - B004-1120	0.997 of 0.997	DISTRICT	TOWN	Date: 05/21/14	ROUTE
Resurface Concrete Surface Treated Gravel	2 8 14 19	Right							DISTRICT	10111		
Bituminous Mix	6 —— 11 —— 16	Grades	Traffic Counters	Crash Locations								BUS-4
Cold Plane and Reclaimed Base Skinny Mix Bituminous Reclaimed Base	Speed Zones	grade up	(counter ID)	Fatal Property Damage Only						DUTI AND TOWN	1 of 1	ETE mileage:
Concrete Concrete	SPEED	grade down	P	Injury Unknown Crash Type					3	RUTLAND TOWN	TWN mileage:	1.432 to 2.429
Concrete	25 30 35 40 45 50 55 60 65				Total Mileage:	0 007 mi		Total Mileage: 0 007 mi			0.0 to 0.997	