

## **Route Log Progress Chart**


DRAFT

Please Note: Errors and Omissions May Exist.


Contact the VTrans Mapping Unit with questions or concerns.

DISTRICT TOWN ROUTE

5 PANTON Maj-0186



**DESCRIPTION BLOCK** 



Historic Projects	Functional Class	Curves	Road Widths	AADT	Mileage by Functional Class By Shee	et	Mileage by Town By Sheet					T
Retreatment Bituminous Gravel	├── <del>+</del> 1 ──── 7	Left	<b>←</b> (ft)	← (count)	0186 7 - Rural - Major Collector		PANTON - S01860115	1.34 of 1.34	DISTRICT	TOWN	Date: 05/21/14	ROUTE
Resurface  Unknown  Bituminous  Surface Treated  Gravel	2 8 — 14 — 19	─ <b>───</b> ─ Right							DISTRICT			
Unknown  Bituminous  Macadam  Plant Mix  Cold Plane and	6 11 16	Grades	Traffic Counters	Crash Locations							1 of 1	Maj-0186
Skinny Mix  Skinny Mix  Cold Flate and Reclaimed Base and Bituminous	Speed Zones	grade up	(counter ID)	Fatal Property Damage Only					5	PANTON	TWN mileage:	ETE mileage:
Bituminous Seal Concrete Concrete  Concrete	25 30 35 40 45 50 55 60 65	grade down	1	Injury Unknown Crash Type	Т	Total Mileage: 1.340 mi	-	Total Mileage: 1.34 mi			0.0 to 1.34	4.68 to 6.02