
VTrans Working to Get You There Vermont Agency of Transportation

Route Log Progress Chart

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Unit with questions or concerns.


DRAFT

DISTRICT TOWN ROUTE
7 LYNDON Maj-0263



DESCRIPTION BLOCK

Bridge 16:
Stringer/multi-beam or girder - 1928
Structure No. 200263001603072
Length: 43'
Width: 21.8'
Facility Carried: TR 06 FAS 263
Bridge Type: ROLLED BEAM
Features Intersected: SHELDON BROOK
Surface: Bituminous
Maintenance/Ownership: Town



| Historic Projects | Functional Class | Curves | Road Widths | AADT | Mileage by Functional Class By She | et | Mileage by Town By Sheet | | | | | |
|--|--|------------|------------------|----------------------------|------------------------------------|-------------------------|--------------------------|------------------------|----------|--------|---------------------|--------------|
| Retreatment Resurface Bituminous Concrete Surface Treated Crowd | → + 1 → 7 → 12 → 17 | Left Right | ← (ft) | (count) | 0263 7 - Rural - Major Collector | 2.610 | LYNDON - S02630307 | 2.61 of 2.61 | DISTRICT | TOWN | Date: 05/21/14 | ROUTE |
| Unknown Bituminous Mix Macadam Plant Mix | 6 — 11 — 16 | Grades | Traffic Counters | Crash Locations | | | | | | | | Maj-0263 |
| Skinny Mix Bituminous Concrete Concrete | Speed Zones SPEED | grade up | (counter ID) | Fatal Property Damage Only | | | | | 7 | LYNDON | 1 of 1 TWN mileage: | ETE mileage: |
| Concrete | 25 30 35 40 45 50 55 60 65 | grade down | ' | Injury Onknown Crash Type | | Total Mileage: 2.610 mi | | Total Mileage: 2.61 mi | | | 0.0 to 2.61 | 0.0 to 2.61 |