

Route Log Progress Chart

Please Note: Errors and Omissions May Exist.
Contact the VTrans Mapping Unit with questions or concerns.

DISTRICT TOWN ROUTE

3 CASTLETON NSH-9150



Bridge 1: Stringer/multi-beam or girder - 1964 Structure No. 203142000111032

Facility Carried: VT 00915 SPUR Bridge Type: ROLLED BEAM

Maintenance/Ownership: State

Surface: Bituminous Maintenance/Ownership: State

Bridge 2: Stringer/multi-beam or girder - 1968 Structure No. 203142000211032

Features Intersected: BRITTAIN BROOK


Under Clearance: 16.42'
Facility Carried: VT 00915 SPUR
Bridge Type: 4 SP ROLLED BEAM
Features Intersected: VT915 CONN. OVER US 4

Length: 69' Width: 30.0'

Length: 262' Width: 30.3'

Surface: Bituminous

DESCRIPTION BLOCK



Historic Projects	Functional Class	Curves	Road Widths	AADT	Mileage by Functional Class By Sheet		Mileage by Town By Sheet					
Retreatment Bituminous Gravel	├── + 1 ── ─ 7 ── ─ 12 ── ─ 17	Left	← (ft)	(count)	3142 7 - Rural - Major Collector	0.398	CASTLETON - S91501103	0.398 of 0.398	DISTRICT	TOWN	Date: 05/22/14	ROUTE
Resurface Concrete Surface Treated Gravel	2 8 — 14 — 19	Right			_				DISTRICT		Date: 03/22/14	ROOIL
Unknown Bituminous Gravel Macadam T Plant Mix	6 11 16											NSH-9150
Bituminous Mix Cold Plane and		Grades	Traffic Counters	Crash Locations							1 of 1	
Skinny Mix Bituminous Reclaimed Base and Bituminous	Speed Zones	- grade up	(counter ID)	Fatal Property Damage Only					9	CASTLETON		ETE mileage:
Bituminous Seal Concrete Concrete	SPEED	grade down	Y	Injury Unknown Crash Type)	CASILLION	TWN mileage:	0.0 to 0.398
Concrete	25 30 35 40 45 50 55 60 65										0.0 to 0.398	