Roadway


Subbase


Road Widths Lane Count


Route Log Progress Chart


DRAFT Please Note: Errors and Omissions May Exist. Contact the VTrans Mapping Unit with questions or concerns.

DISTRICT TOWN ROUTE SHELDON VT-78









Maintenance Gar	age	District 8 - Highgate Garage				
		0		 		
Traffic Counters	5	S6F335				
Functional Class		7		 		
FullCubilal Class		"				
Speed Zone						
•				 		
	2012	1600				
	1800	1600	į			
	2011	4000				
AADT Counts	2010 4 1900	1600				
	2009	1500	j			
	1000	1400				
	2008	1400	—			
	2012]				
Crash Locations	2010					
	2009	ı				
	2008	I I				

DESCRIPTION	BI OC
DESCRIPTION	BLUC

Culvert 14: Culvert - 1956 Structure No. 300296001406141 Length: 8' Under Clearance: 5.0' Facility Carried: VT78 Bridge Type: RC BOX Features Intersected: BROOK Maintenance: State Culvert 16: Culvert - 1958 Structure No. 300296001606141 Length: 13' Under Clearance: 10.0' Facility Carried: VT78 Bridge Type: RC BOX Features Intersected: MCGOWAN BROOK Maintenance: State