VITANS Working to Get You There Vermont Agency of Transportation

Route Log and Progress Chart

DRAFT


Please Note: Errors and Omissions May Exist.

Contact the VTrans Mapping Section with questions or concerns.

DISTRICT	TOWN	ROUTE
5	MILTON	Urb-5806



Urb-5806



STRUCTURE DESCRIPTIONS									
Bridge D82: Stringer/multi-beam or girder - 1967 Structure No. 2004100D8204101 Length: 246' Width: 29.8' Under Clearance: 16.75' Facility Carried: TR 00TH3 Bridge Type: 4 SPAN ROLLED BEAM Features Intersected: TH NO 3 OVER I 89 Surface: Bituminous Maintenance/Ownership: State									

Historic Projects	Functional Class	Curves	Road Widths	AADT	Mileage by Functional Class By Sheet		Mileage by Town By Sheet					
Unknown Bituminous Concrete Surface Treated	1 - Interstate 3 - Principal 5 - Major System Collector	(degrees) Left	← (ft)	← (count)	5806 5 - Major Collector	8.180	MILTON - S58060410	8.18 of 8.18	DISTRICT	TOWN	Date: 11/12/16	ROUTE
Retreatment Bituminous Macadam Gravel	2 - Other 4 - Minor Arterial 6 - Minor Collector	Right							DISTRICT		2 410: 12, 12, 10	
Resurface Cold Plane and Plant Mix	Freeways and Arterial Collector		T - (C - C - 11 - 1									Urb-5806
Bituminous Mix Bituminous Concrete Reclaimed Base and Reclaimed Base and	Lxpressways	Grades	Traffic Counters	Crash Locations							1 of 1	
Skinny Mix Concrete — Bituminous Concrete	Speed Zones	grade up (percent) grade down	Υ	Fatal Property Damage Only						MILTON	l l	ETE mileage:
Bituminous Seal Gravel	SPEED	grade down	(counter ID)	Injury Unknown Crash Type					3	HILLOIT	TWN mileage:	0.0 to 8.18
Indicated plans available - http://vtransmap01.aot.state.vt.us/rp/dpr/Dlwebstore/	25 30 35 40 45 50 55 60 65				Page Total M	ileage: 8.180 mi		Page Total Mileage: 8.18 mi			0.0 to 8.18	