DISTRICT TOWN ROUTE DRAFT Route Log and Progress Chart Please Note: Errors and Omissions May Exist. WESTMINSTER, ROCKINGHAM I-91 Contact the VTrans Mapping Section with questions or concerns. Base Map ROCKINGHAM WESTMINSTER SOUTH BELLOWS FALLS VILLAGE 1 in = 0.6 milesStick Diagram STRUCTURE DESCRIPTIONS Intersecting State Routes (excl. ramps/approaches) Other Intersecting Highways, Ramps, +-+-++ Railroad Crossings Primary Structures Bridge <mark>19-4</mark>: Culvert - 1963 Secondary Structures Structure No. 30009119-413201 Divided State Highway Length: 12' State Highway Under Clearance: 10.0' Facility Carried: I91 Divided Town Highway Structure Type: RC BOX ---- Town Highway Features Intersected: BROOK Streams (Hydraulic Structure) Maintenance: State Town Boundary - - - Village/UC Boundaries Bridge 19-5: Culvert - 1963 --- District Boundaries o - o - State/Town Highway Change Structure No. 30009119-513201 Length: 10' Under Clearance: 8.0' --- Divided Highway Limits ---- Ghost Section Boundary Facility Carried: I91 ----- Federal Urban Area Limits Structure Type: RC BOX Features Intersected: BROOK Scale: 1 INCH = 2,000 FEET Maintenance: State Stringer/multi-beam or girder - 1963 Structure No. 200091020S13202 Travellane Length: 163' Roadway Width: 30.0' **Road Widths** Lane Count Under Clearance: 15.5' Two 2 1/2" Pen. Mac. Cr. St. Base Courses Facility Carried: I 91 ML Structure Type: 3 SPAN ROLLED BEAM Subbase Two·2-1/2"·Cr.-Gravel·Plant·Mix·Base·Co Features Intersected: I 91 OVER WSTMSTER SH Surface: Bituminous Maintenance/Ownership: State Curves Bridge 21S: Stringer/multi-beam or girder - 1963 Structure No. 200091021S13202 Grades Width: 30.0' Under Clearance: 19.25' **Guardrails** — Facility Carried: I 91 ML Structure Type: 8 SPAN ROLLED BEAM Features Intersected: I 91 OVER TH 1 SAXTON **Rumblestrips** Surface: Bituminous Maintenance/Ownership: State Bridge <mark>21-2</mark>: Culvert - 1963 Structure No. 30009121-213141 Under Clearance: 5.0' Facility Carried: I91 Structure Type: RC BOX Features Intersected: WATER MAIN SLEEVE Maintenance: State Historic Projects Bridge 21-3: Culvert - 2001 Structure No. 30009121-313141 1994: IR 091-1(18) C/1 Length: 10' Under Clearance: 6.0' Facility Carried: I91 Structure Type: SEGMENTAL RC BOX Features Intersected: WEBB BROOK Maintenance: State Bridge 22S: Stringer/multi-beam or girder - 1963 Structure No. 200091022S13142 District 2 - DMF Maintenance Rockingham Garage **Maintenance Garage** Length: 84' Width: 38.0' Under Clearance: 13.33' Facility Carried: I 91 ML Speed Zone Structure Type: ROLLED BEAM Features Intersected: I 91 OVER TH NO 46 Surface: Bituminous **Functional Class** Maintenance/Ownership: State NHS - Interstate (National Highway System Stringer/multi-beam or girder - 1963 Structure No. 200091023S13142 Length: 157' Width: 42.0' **Limited Access Highway** Under Clearance: 14.83' Facility Carried: I 91 ML Structure Type: 3 SPAN ROLLED BEAM Interstate Or Divided Highway **Customer Service Level** Features Intersected: I 91 OVER VT 103 Surface: Bituminous Maintenance/Ownership: State **Traffic Counters** Bridge <mark>24S</mark>: Truss - deck - 1965 Structure No. 200091024S13142 Length: 851' Width: 30.0' 5310 4463 7008 6878 5524 5951 Under Clearance: 100.0' Facility Carried: I 91 ML Structure Type: 4 SPAN STL DK TRUSS **AADT** Features Intersected: I 91 OVER GM RR WLMSR Surface: Bituminous 2017 Maintenance/Ownership: State

(Incomplete) 2021

2017

Crash Locations 2019