


Route Log and Progress Chart


DRAFT Please Note: Errors and Omissions May Exist. Contact the VTrans Mapping Section with questions or concerns.


Page Total Mileage: 4.854 mi

DISTRICT TOWN ROUTE US-7 **SHELBURNE**

Page Total Mileage: 4.854 mi







STRUCTURE DESCRIPTIONS

Bridge <mark>143</mark>: Culvert - 1956 Structure No. 300019014304131 Length: 12' Under Clearance: 10.0' Facility Carried: US7 Structure Type: RC BOX Features Intersected: CLARK FARM BROOK Maintenance: State

Stringer/multi-beam or girder - 2001 Structure No. 200019014404132 Length: 275' Width: 53.3' Facility Carried: US 07 ML Structure Type: 3 SP CONT CUR PL GIR Features Intersected: LAPLATTE RIVER Surface: Bituminous Maintenance/Ownership: State

Bridge 145: Culvert - 2005 Structure No. 300019014504131 Length: 17' Facility Carried: US7 Structure Type: SEGMENTAL RC BOX Features Intersected: MUNROE BROOK Maintenance: State

ROUTE TOWN Date: 11/17/21 1 of 1 ETE mileage: **SHELBURNE** TWN mileage: 123.823 to 128.677 0.0 to 4.854

2 - Other 4 - Minor Arterial

Retreatment Bituminous Macadam

Skinny Mix Concrete

Cold Plane and
Bituminous Concrete
Concrete

Plant Mix
Reclaimed Base and
Bituminous Concrete

Collector

Left (percent) grade up

Weigh-In-Motion (WIM)

△ Short-Term, Unscheduled

High Crash Locations (HCL's)

HCL No. 201 - 300 (21 - 30)

1 - 100 (1 - 10) 301 - 400 (31 - 40)

Sections (& Intersections)

▲ Short-Term, Scheduled