

Route Log and Progress Chart

Please Note: Errors and Omissions May Exist. Contact the VTrans Mapping Section with questions or concerns.


DRAFT

DISTRICT TOWN ROUTE CLARENDON US-7

Page Total Mileage: 5.656 mi







RUCTURE	DESCRIPTIONS

Stringer/multi-beam or girder - 1967 Structure No. 200019090S11052 Structure Type: 4 SPAN ROLLED BEAM Features Intersected: MILL RIVER Maintenance/Ownership: State

Structure No. 300019009211051 Features Intersected: BROOK

Structure No. 300019009311051 Features Intersected: CATTLE PASS

Structure No. 300019009511051 Features Intersected: BROOK

Stringer/multi-beam or girder - 1968 Structure No. 200019009611052 Structure Type: WELDED PLATE GIRDER Features Intersected: COLD RIVER Surface: Bituminous Maintenance/Ownership: State

Page Total Mileage: 5.656 mi